

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AN206  
SSW  
1/4-1/2  
0.332 mi.  
1755 ft.

MAN HOLE #40789  
STILLWELL AV & SURF AV  
BROOKLYN, NY

NY Spills S103575742  
N/A

Site 4 of 6 in cluster AN

Relative:  
Higher

Actual:  
6 ft.

SPILLS:

Name: MAN HOLE #40789  
Address: STILLWELL AV & SURF AV  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9811906 / 2003-02-20  
Facility ID: 9811906  
Facility Type: ER  
DER Facility ID: 87878  
Site ID: 98824  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1998-12-22  
Investigator: CAENGELH  
Referred To: Not reported  
Reported to Dept: 1998-12-22  
CID: 257  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1998-12-22  
Spill Record Last Update: 2003-02-24  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: JOE DEVOTI  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was ENGELHARDT e2mis 122094 12/22/98 10:00 S. RADCLIFFE-31912-O.S. CABLE-ON ROUTINE INSPECTIONS FD APPROX 1QT OF UNKNOWN OIL ON APPROX 800 GAL OF WATER IN M/H 40789 W/S STILLWELL AVE N/O SURF AVE. UNDIAPERABLE-NO SEWERS OR WATERWAYS AFFECTED AND IS CONTAINED. NO SUMP PUMP IN MH.TOOK SAMPLE W/4-6 HR PRIORITY AND PLACE ENV TAG#14345 NOTIFIED CIG-J DEVOTI @ 10:38 JAP-56037 UPDATE - 12/22/98 5:25 PM - CHEM LAB RESULTS <1PPM LAB SEQ # 98-14228 UPDATE - 12/29/98 1918HR - CLEAN UP COMPLETE WITH SLIX AS OF 1840HRS - ENV STOP TAG 14345 REMOVED AS PER FLUSH OPERATOR N. SAVOCA #17932 TRUCK # 60532 --C.NEVILLE - # 19661 INCIDENT IS CLOSED."

Remarks: "1 quart on water in the manhole smaples taken ref #122094 "

All Materials:

Site ID: 98824  
Operable Unit ID: 1072624  
Operable Unit: 01  
Material ID: 312186  
Material Code: 0066A  
Material Name: unknown petroleum

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported